



409S® Stainless Steel


Installation diagram for:

SYSTEM #81071


2 1/2" MANIFOLD DOWNPIPES

1964-77 BIG BLOCK CHEVROLET VEHICLES

NOT FOR USE WITH HEAT RISER VALVE



HARDWARE
INCLUDED:



SF012 (2)



GA108 (2)



TB515S (2)